


# HUMIDITY / TEMPERATURE / TRANSMITTER

**High Temperature Humidity – Wet and Dry Bulb**

0 – 100.0% RH      0 – 100.0 °C

Comprising

- Temperature Transmitter - Model TH-4001 – AC 85 / 265V
- Input 2 x 3 wire PT100 ohm RTD Sensors
- Output – DC 0-1 V
- Range 0 – 100 % RH
- Range 0 – 100 °C



Requirements for RH / Temperature Indicator / Controller

- 1 only Temperature Transmitter – Model TH-4001
- 2 only PT100  $\Omega$  RTD Sensors
- 1 only Shinko JCS 33A SM – scale 0-100.0 % for RH.
- 1 only Shinko JCS 33A SM – scale 0-100.0 °C for temperature.
- Constant water level bath

## Temperature Controls Pty Ltd

Sydney: 7 Yamma St Sefton NSW 2162 Ph: (02) 9721 8644 Fx (02) 9738 9339

Melbourne: 8/280 Whitehall St Yarraville VIC 3013 Ph: (03) 9687 0000 Fx: (03) 9687 1900

Web : [www.temperature.com.au](http://www.temperature.com.au) Email: [sales@temperature.com.au](mailto:sales@temperature.com.au)